


FIG. 1 (PRIOR ART)



US 4,438,910 A








FIG. 3



002740" 0004700

FIG. 4





→  
TIME

1. The first step is to identify the problem. This involves understanding the current situation and the goals that need to be achieved.

FIG. 6





FIG. 7



002120" 00211960

FIG. 8






FIG. 9




FIG. 10






FIG. 11








FIG. 13A




FIG. 13B

FIG. 14




FIG. 15




FIG. 16






FIG. 17A




FIG. 17B



FIG. 17C




FIG. 17D




FIG. 17E




FIG. 17F



FIG. 17G




FIG. 18A




FIG. 18B




FIG. 19A



FIG. 19B




FIG. 19C




FIG. 19D




FIG. 19E




FIG. 19F



FIG. 19G




FIG. 20A




FIG. 20B




FIG. 21A




FIG. 21B




FIG. 21C




FIG. 21D




FIG. 21E




FIG. 21F



FIG. 21G




FIG. 22A




FIG. 22B

